

PORT AUTHORITY & TENANT
ASBESTOS ABATEMENT PROJECTSDate: 08/13/96
PAGE NUMBER 1AP=ACOUSTICAL PLASTER
FP=FIREFPROOFING

Ct	Building	Bestquant	Product	Continum Jobnum	Start Date	Reason
1	WTC-T	68000SF/70000SF	FP/VAT	WTC-115.221 115.221	12/18/87	RENOVATION & ALTERATION OF SPACE TO ACCOMDATE NEW TENANTS
T	WTC-1		FP FALLOUT	WTC-115.224 115.224	05/16/91	EMERGENCT CLEANUP
1	WTC-1	35000SF	FP	WTC-115.225 115.225	12/01/87	INSTALLATION OF SPRINKLER SYSTEMS AND DEMOLITION AND ALTERATION OG SPACE ALSTERB
1	WTC-1	2400SF	FP	EKO-100.367 115.227	11/06/87	DEMOLITION AND ALTERATION OF SPACE TO ACCOMDATE NEW TENANT
1	WTC-1	62244SF/35000SF	FP/VAT	WTC-115.225 115.233	06/03/88	INSTALLATION OF SPRINKLER SYSTEMS-DEMOLITION & ALTERATION OF SPACE TO ACCOMDATE NEW TENANT
1	WTC-1	60000SF/35000SF	FP/VAT	WTC-115.229 115.235	03/01/89	INSTALLATION OF SPRINKLER SYSTEMS-DEMOLITION AND ALTERATION OF SPACE TO ACCOMDATE NEW TENANT
T	WTC-1	60000SF/35000SF	FP/VAT	WTC-115.229 115.236	02/01/88	INSTALLATION OF SPRINKLER SYSTEMS-DEMOLITION AND ALTERATION OF SPACE TO ACCOMDATE NEW TENANT
1	WTC-1	60000SF/35000SF	FP/VAT	WTC-115.229 115.238	05/01/88	INSTALLATION OF SPRINKLER SYSTEMS-DEMOLITION & ALTERATION OF SPACE TO ACCOMDATE NEW TENANT
1	WTC-1	62244SF/35000SF	FP/VAT	WTC-115.230 115.240	03/01/89	INSTALLATION OF SPRINKLER SYSTEMS-DEMOLITION & ALTERATION OF SPACE TO ACCOMDATE NEW TENANT
1	WTC-1	25SF/2,400SF	FP/SURFACE AREA CLEANED	WTC-115.224 115.241	12/05/88	O&M REPAIR OF MAIN SPRINKLER SUPPLY PIPE-FP ADJACENT TO PIPE REMOVED (8 LOCATIONS)
T	WTC-T	2,540SF	FP	WTC-115.224 115.242	03/27/89	RENOVATION & ALTERATION OF SPACE TO ACCOMDATE NEW TENANT
T	WTC-1	300SF	FP	WTC-115.224 115.243	02/17/89	RENOVATION - RECONSTRUCTION OF RECENTLY ABATED 16TH FLOOR REQUIRES INSTALLATION OF PLUMBING ROUTED THROUGH FLOOR ON 16\CEILING ON 15



PORT AUTHORITY & TENANT
ASBESTOS ABATEMENT PROJECTS

Date:08/13/96
PAGE NUMBER 2

AP=ACOUSTICAL PLASTER
FP=FIREPROOFING

Ct Building	Bestquant	Product	Contrnum Jobnum	Start Date	Reason
1 WIC-1	59500SF/35000SF	FP/VAT	WIC-115.231 115.244	09/01/89	INSTALLATION OF SPRINKLER SYSTEMS AND DEMOLITION AND ALTERATION OF SPACE TO ACCOMMODATE NEW TENANT
1 WTC-1	68000SF/35000SF	FP/VAT	WTC-115.232 115.245	04/30/90	INSTALLATION OF SPRINKLER SYSTEMS AND DEMOLITION AND ALTERATION OF SPACE TO ACCOMMODATE NEW TENANT
1 WTC-1	62240SF/35000SF	FP/VAT	WTC-115.231 115.250	08/20/90	RENOVATION - INSTALLATION OF SPRINKLER SYSTEMS IN PREPARATION FOR MARKETING OF SPACE
1 WIC-1	18000SF/30000SF	FP/VAT	WIC-115.231 115.251	10/01/90	RENOVATION - INSTALLATION OF SPRINKLER SYSTEMS REVISED 7/'90 TO INCLUDE VAT, WHICH TENANTS SAMPLED
1 WTC-1	36000SF/35000SF	FP/VAT	WIC-115.235 115.252	05/01/93	RENOVATION - INSTALLATION OF SPRINKLER SYSTEMS IN PREPARATION FOR MARKETING OF SPACE
1 WTC-1	68000SF/35000SF	FP/VAT	WTC-115.232 115.253	12/10/90	RENOVATION - INSTALLATION OF SPRINKLER SYSTEMS IN PREPARATION FOR MARKETING OF SPACE
1 WTC-1	68000SF/35000SF	FP/VAT	WTC-115.232 115.254	04/02/91	INSTALLATION OF SPRINKLERS AND MARKETING OF SPACE
1 WTC-1	36000SF/35000SF	FP/VAT	WTC-115.233 115.261	03/15/93	INSTALLATION OF SPRINKLERS AND SPACE MARKETABILITY
1 WIC-1	40000SF/40000SF	FP/VAT	WTC-115.264 115.264	01/01/96	RENOVATION
1 WTC-1	72000SF	FP/VAT	WIC-115.265 115.265	03/01/93	RENOVATION
1 WTC-1	40000SF/40000SF	FP/VAT	WIC-115.269 115.269	05/31/96	RENOVATION
1 WIC-1	36000SF/36000SF	FP/VAT	WIC-115.271 115.271	03/01/96	RENOVATION
1 WTC-1	68000SF/35000SF	FP/VAT	WTC-115.272 115.272	06/01/95	RENOVATION

PORT AUTHORITY & TENANT
ASBESTOS ABATEMENT PROJECTS

Date:08/13/96
PAGE NUMBER 3

AP=ACOUSTICAL PLASTER
FP=FIREPROOFING

Ct	Building	Bestquant	Product	Contnum Jobnum	Start Date	Reason
1	WTC-1	32000SF/35000SF	FP/VA1	WTC-115.280 115.280	01/11/94	INSTALLATION OF SPRINKLERS AND MARKETABILITY OF SPACE
1	WTC-1		FP	MF-415.750 115.304	08/02/93	
T	WTC-1	5SF	FP	WTC-115.510 115.306	02/25/95	EMERGENCY RENOVATION
1	WTC-1		FP	WTC-115.510 115.307	03/03/95	STANDBY CLEANUP FOR NON-ACH DEMO PRIOR TO ABATEMENT
1	WTC-1		FP-CLEANUP	WTC-115.510 115.309	03/13/95	IRC CLEANUP
1	WTC-1		FP CLEANUP	WTC-115.510 115.310	03/29/95	STANDBY DURING CEILING TILE REPAIR OF FLOODED MENS' ROOM
1	WTC-T	SPOT	FP	WTC-115.510 115.311	03/27/95	ADA COMPLIANCE
1	WTC-1		FP CLEANUP	WTC-115.510 115.313	04/18/95	EMERGENCY-FALLOUT
1	WTC-1		FP	WTC-115.510 115.314	05/05/95	CLEANUP FOR LIGHT FIXTURE REPLACEMENT
1	WTC-T		FP/CONTAMINATED CEILING TILE	WTC-115.510 115.315	05/09/95	
1	WTC-T		FP FALLOUT	WTC-115.510 115.317	05/11/95	FALLOUT-EMERGENCY
T	WTC-1		FP FALLOUT	WTC-115.510 115.318	05/12/95	EMERGENCY CLEANUP
T	WTC-1		FP FALLOUT CLEANUP-EMERGEN CY	WTC-115.510 115.320	05/13/95	EMERGENCY
1	WTC-1		FP	WTC-115.510 115.321	05/19/95	NEGATIVE INSULATION DN LINE IN PLENUM (FP ON BEAMS)
T	WTC-1		FP FALLOUT	WTC-115.510 115.324	06/13/95	EMERGENCY
1	WTC-T		FP	WTC-115.510 115.331	09/14/95	REPAIR & INSTALLATION OF DRAIN LINE

PORT AUTHORITY & TENANT
ASBESTOS ABATEMENT PROJECTS

Date:08/13/96
PAGE NUMBER 4

AP=ACOUSTICAL PLASTER
FP=FIREPROOFING

Ct	Building	Bestquant	Product	Contrnum Jobnum	Start Date	Reason
1	WTC-1		FP	WTC-115.510 115.339	12/08/95	EMERGENCY CLEAN-UP
1	WTC-1		FP	WTC-115.510 115.340	12/29/95	EMERGENCY CLEAN-UP OF FALLOUT ACM
1	WTC-1		FP	WTC-115.510 115.341	01/04/96	EMERGENCY CLEAN-UP OF FALLOUT ACM
1	WTC-1		FP	WTC-115.510 115.342	12/09/05	FALL-OUT
1	WTC-1		FP	WTC-115.510 115.343	01/09/06	FALLOUT OF ACM
1	WTC-1		FP	WTC-115.510 115.344	01/28/96	EMERGENCY FP FALL-OUT
1	WTC-1		FP	WTC-115.510 115.354	05/02/96	FALLOUT OF FIREPROOFING MATERIAL
1	WTC-1		FP	WTC-115.510 115.355	05/06/96	FALLOUT OF FIREPROOFING MATERIAL
1	WTC-1	100SF	FP	WTC-115.224 115.701	02/13/89	O&M - INSTALLATION OF NEW VALVES
1	WTC-1	125SF	FP	WTC-115.224 115.703	09/08/89	IRC - DAMAGED CONDITION OF ACM AND POTENTIAL FOR EXPOSURE
1	WTC-1	750SF	FP	WTC-115.224 115.704	03/20/89	O&M - RE-ENFORCEMENT OF STRUCTURAL STEEL
1	WTC-1	35,000SF	FP	WTC-115.224 115.708	08/28/89	IRC - SURFACE CLEANED
1	WTC-1	2800SF/700SF	FP/VAT	WTC-115.224 115.709	07/01/89	IRC - DETERIORATED CONOITION
1	WTC-1	200SF	FP	WTC-115.224 115.714	06/24/89	INSTALLATION OF SPRINKLER SYSTEMS AND DEMOLITION AND RENOVATION OF FLOOR TO ACCOMMODATE NEW TENANT
1	WTC-1	80SF	FP	WTC-115.224 115.715	08/05/89	DEMOLITON AND RENOVATION OF FLOOR TO ACCOMMODATE NEW TENANT
1	WTC-1	80SF	FP	WTC-115.224 115.716	09/15/89	INSTALLATION OF SPRINKLER SYSTEMS AND DEMOLITION AND ALTERATION OF FLOOR TO

PORT AUTHORITY & TENANT
ASBESTOS ABATEMENT PROJECTS

Date:08/13/96
PAGE NUMBER 5

AP=ACOUSTICAL PLASTER
FP=FIREPROOFING

Ct	Building	Bestquant	Product	Continum Jobnum	Start Date	Reason
						ACCOMMODATE NEW TENANT
1	WTC-1	80SF	FP	WTC-115.224 115.717	09/15/89	DEMOLITION AND RENOVATION OF SPACE TO ACCOMMODATE NEW TENANT
1	WTC-1	120SF	FP	WTC-115.224 115.718	12/22/89	DEMOLITION AND RENOVATION OF FLOOR TO ACCOMMODATE NEW TENANT
1	WTC-1	140SF	FP	WTC-115.224 115.719	12/22/89	DEMOLITION AND RENOVATION OF FLOOR TO ACCOMMODATE NEW TENANT
1	WTC-1	35,000SF	FP	WTC-115.224 115.723	11/06/89	O&M - CLEAN-UP OF FALLOUT MATERIAL
1	WTC-1	513SF	FP	WTC-115.224 115.737	08/20/90	RENOVATION
1	WTC-1	4SF	FP	WTC-115.224 115.741	02/25/91	INSTALLATION OF NEW EXIT DOORS
1	WTC-1		FP	WTC-115.224 115.758	10/28/89	EMERGENCY CONDITION
1	WTC-1		FP	WTC-115.224 115.759	11/13/89	EMERGENCY CONDITION
1	WTC-1		FP	WTC-115.224 115.760	11/16/89	EMERGENCY CONDITION
1	WTC-1		FP	WTC-115.224 115.761	11/21/89	EMERGENCY CONDITION
1	WTC-1		FP	WTC-115.224 115.762	01/13/90	EMERGENCY CONDITION
1	WTC-1		FP	WTC-115.224 115.763	01/24/90	EMERGENCY CONDITION
1	WTC-1		FP	WTC-115.224 115.766	03/20/90	EMERGENCY CONDITION
1	WTC-1	3626SF	FP FALLOUT	WTC-115.224 115.769	07/27/90	EMERGENCY CONDITION
1	WTC-1	3626SF	FP FALLOUT	WTC-115.224 115.770	07/28/90	EMERGENCY CONDITION
1	WTC-1	140SF/1450SF	FP FALLOUT/FP FALLOUT	WTC-115.224 115.771	08/07/90	EMERGENCY CONDITION

PORT AUTHORITY & TENANT
ASBESTOS ABATEMENT PROJECTS

Date:08/13/96
PAGE NUMBER 6

AP=ACOUSTICAL PLASTER
FP=FIREPROOFING

Ct	Building	Bestquant	Product	Construm Jobnum	Start Date	Reason
1	WTC-1	3914SF	FP FALLOUT	WTC-115.224 115.772	07/31/90	EMERGENCY CONOITION
1	WTC-1	688SF	FP FALLOUT	WTC-115.224 115.775	11/07/90	EMERGENCY CONOITION
1	WTC-1	40SF	FP FALLOUT	WTC-115.224 115.780	05/31/91	CLEAR FLOOR FOR O&M WORK
1	WTC-1	<5SF	FP	WTC-115.224 115.785	10/29/91	RENOVATION - ABATEMENT OF FP ON MOLO FOR '92
1	WTC-1	7000SF	FP	WTC-115.224 115.788	03/01/92	
1	WTC-1	54SF	FP FALLOUT	WTC-115.224 115.794	08/19/91	EMERGENCY CLEANUP
1	WTC-1	216SF	FP FALLOUT	WTC-115.224 115.795	04/18/91	EMERGENCY CLEANUP
1	WTC-1	432SF	FP FALLOUT	WTC-115.224 115.815	03/14/92	EMERGENCY CONOITION
1	WTC-1	837SF	FP FALLOUT	WTC-115.224 115.817	03/11/92	EMERGENCY CONOITION
1	WTC-1	243SF	FP FALLOUT	WTC-115.224 115.818	03/09/92	EMERGENCY CONOITION
1	WTC-1	1053SF	FP FALLOUT	WTC-115.224 115.819	03/12/92	EMERGENCY CONOITION
1	WTC-1	324SF	FP FALLOUT	WTC-115.224 115.821	03/25/92	EMERGENCY CONOITION
1	WTC-1	5913SF	FP FALLOUT	WTC-115.224 115.823	04/06/92	EMERGENCY CONOITION
1	WTC-1	162SF	FP FALLOUT	WTC-115.224 115.829	04/10/92	EMERGENCY CLEANUP
1	WTC-1	25 BAGS	FP FALLOUT/MISC	WTC-115.224 115.831	10/09/92	NO ABATEMENT PER JOB, ONLY DISPOSAL
1	WTC-1	384SF	FP	WTC-115.224 115.832	07/20/90	RENOVATION
1	WTC-1		FP FALLOUT	WTC-115.224 115.833	02/05/91	EMERGENCY

PORT AUTHORITY & TENANT
ASBESTOS ABATEMENT PROJECTS

Date:08/13/96
PAGE NUMBER 7

AP=ACOUSTICAL PLASTER
FP=FIREPROOFING

Ct	Building	Bestquant	Product	Contrnum Jobnum	Start Date	Reason
1	WTC-1	13000SF	FP	WTC-115.224 115.834	10/15/92	EMERGENCY CONDITION
1	WTC-1		FP FALLOUT	WTC-115.224 115.836	06/17/92	EMERGENCY CLEANUP
1	WTC-1		FP FALLOUT	WTC-115.224 115.837	06/19/92	EMERGENCY CLEANUP
1	WTC-1	162SF	FP FALLOUT	WTC-115.224 115.838	07/14/92	EMERGENCY CLEANUP
1	WTC-1	300SF	FP FALLOUT	WTC-115.224 115.839	07/22/92	EMERGENCY CLEANUP
1	WTC-1	243SF	FP FALLOUT	WTC-115.224 115.840	08/03/92	EMERGENCY CLEANUP
1	WTC-1	11000SF/11000SF	FP/VAT	WTC-115.224 115.849	07/15/93	INSTALLATION OF VAULTS FOR BANK OF AMERICA ON 18TH FLOOR
1	WTC-1	15000SF/15000SF	FP/VA1	WTC-115.224 115.850	08/01/93	INSTALLATION OF VAULTS FOR BANK OF AMERICA ON 23RD FLOOR
1	WTC-1		FP FALLOUT	WTC-115.224 115.852	11/09/92	EMERGENCY CLEANUP
1	WTC-1		FP FALLOUT	WTC-115.224 115.853	11/30/92	EMERGENCY CLEANUP
1	WTC-1		FP FALLOUT	WTC-115.224 115.854	12/07/92	EMERGENCY CLEANUP
1	WTC-1		FP FALLOUT	WTC-115.224 115.855	12/10/92	EMERGENCY CLEANUP
1	WTC-1		FP FALLOUT	WTC-115.224 115.856	12/11/92	EMERGENCY CLEANUP
1	WTC-1		FP FALLOUT	WTC-115.224 115.859	12/29/92	EMERGENCY CLEANUP
1	WTC-1		FP FALLOUT	WTC-115.224 115.860	08/05/92	EMERGENCY CLEANUP
1	WTC-1		FP FALLOUT	WTC-115.224 115.861	08/11/92	EMERGENCY CLEANUP
1	WTC-1		FP FALLOUT	WTC-115.224 115.862	08/13/92	EMERGENCY CLEANUP

PORT AUTHORITY & TENANT
ASBESTOS ABATEMENT PROJECTS

Date:08/13/96
PAGE NUMBER 8

AP=ACOUSTICAL PLASTER
FP=FIREPROOFING

Ct	Building	Bestquant	Product	Contrnum Jobnum	Start Date	Reason
1	WTC-1		FP FALLOUT	WTC-115.224 115.863	08/26/92	EMERGENCT CLEANUP
1	WTC-1		FP FALLOUT	WTC-115.224 115.865	11/05/92	EMERGENCT CLEANUP
1	WTC-1		FP FALLOUT	WTC-115.224 115.866	07/02/93	EMERGENCY CLEANUP
1	WTC-1		FP FALLOUT	WTC-115.224 115.867	01/12/93	EMERGENCT CLEANUP
1	WTC-1		FP FALLOUT	WTC-115.224 115.868	04/30/93	EMERGENCY CLEANUP
1	WTC-1		FP FALLOUT	WTC-115.224 115.869	06/06/93	EMERGENCY O&M ABATEMENT WORK
1	WTC-1		FP	WTC-115.224 115.870	09/10/93	NEW ELEVATOR OPENING ON A-11, ONE WTC
1	WTC-1		FP FALLOUT	WTC-115.224 115.871	06/11/93	EMERGENCY CLEANUP FOR ELEVATOR SHAFTS
1	WTC-1		FP FALLOUT	WTC-115.224 115.872	06/10/93	EMERGENCT O&M ABATEMENT WORK
1	WTC-1		FP FALLOUT	WTC-115.224 115.873	06/25/93	EMERGENCT CLEANUP WORK
1	WTC-1		FP FALLOUT	WTC-115.224 115.874	06/25/93	EMERGENCY O&M ABATEMENT AND CLEANUP WORK DUE TO INSTALLATION OF CONDUITS FOR BANK OF AMERICA,
1	WTC-1		FP FALLOUT	WTC-115.224 115.875	06/25/93	EMERGENCT CLEANUP
1	WTC-1		FP FALLOUT	WTC-115.224 115.876	06/30/93	EMERGENCT O&M ABATEMENT AND CLEANUP WORK
1	WTC-1	15000\$F	FP	WTC-115.224 115.877	09/15/93	SEVERE DELAMINATION THOUGHOUT SHAFTS
1	WTC-1		FP FALLOUT	WTC-115.224 115.878	07/15/93	EMERGENCY CLEANUP
1	WTC-1		FP FALLOUT	WTC-115.224 115.881	04/07/92	EMERGENCY CLEANUP

PORT AUTHORITY & TENANT
ASBESTOS ABATEMENT PROJECTS

Date:08/13/96
PAGE NUMBER 9

AP=ACOUSTICAL PLASTER
FP=FIREPROOFING

Ct	Building	Bestquant	Product	Continum Jobnum	Start Date	Reason
T	WTC-1		RE-FP	WTC-115.224 115.886	08/17/93	EMERGENCY REFIREPROOFING, ACM ON BEAMS
1	WTC-1	60SF	FP	WTC-115.224 115.892	11/04/93	EMERGENCY REFIREPROOFING, ACM ON BEAMS
1	WTC-1	30100SF	FP/DUCT INSULATION	WTC-115.510 115.893	01/01/94	DEMOLITION OF FLOOR
1	WTC-1		FP FALLOUT	WTC-115.224 115.894	08/28/93	EMERGENCY CLEANUP
1	WTC-1		FP	WTC-115.224 115.901	11/19/93	INSTALLATION OF DRAIN LINES ON 18TH FLOORS
1	WTC-1	40CYDS	FP/VAT	WTC-115.224 115.908	01/07/94	EMERGENCY CLEANUP
1	WTC-1		FP FALLOUT	WTC-115.224 115.909	01/06/94	EMERGENCY CLEANUP
1	WTC-1		ACM ON STEEL (FP)	WTC-115.510 115.914	01/28/94	INSPECTION OF BEAMS
1	WTC-1		FP	WTC-115.510 115.919	03/15/94	SPOT REMOVAL FOR DRAINS
1	WTC-1		FP	WTC-115.510 115.927	05/15/94	INSPECTION OF STEEL FOR INTEGRITY
1	WTC-1	20LF	FP	WTC-115.510 115.928	04/08/94	ENCAPSULATION OF LOOSE FP
T	WTC-1	CLEANUP-TOP & INTERIOR 2 CARS	FP FALLOUT	WTC-115.510 115.931	04/19/94	EMERGENCY CLEANUP
1	WTC-1	CLEANUP-TOP & INTERIOR OF CARS 12 & 13	FP FALLOUT	WTC-115.510 115.932	04/23/94	EMERGENCY CLEANUP
1	WTC-1		FP	WTC-115.510 115.936	05/31/94	ACCESS DOORS TO SHAFTS
1	WTC-1		FP FALLOUT	WTC-115.510 115.939	06/28/94	
1	WTC-1		FP	WTC-115.510 115.940	06/29/94	INSTALLATION OF FIBER OPTICS CABLE

PORT AUTHORITY & TENANT
ASBESTOS ABATEMENT PROJECTS

Date:08/13/96
PAGE NUMBER 10

AP=ACOUSTICAL PLASTER
FP=FIREPROOFING

Ct Building	Bestquant	Product	Continuum Jobnum	Start Date	Reason
T WTC-1		FP CLEANUP	WTC-115.510 115.941	07/05/94	
1 WTC-1		FP	WTC-115.510 115.943	07/22/94	
1 WTC-1		FP/CEILING	WTC-115.510 115.948	08/25/94	EMERGENCY CLEANUP
T WTC-1		FP	WTC-115.510 115.952	09/14/94	RENOVATION (FOR A.O.A.)
1 WTC-1	1000SF	FP	WTC-115.510 115.954	09/26/94	EMERGENCY FLOOD CLEANUP,
1 WTC-1	2000SF	FP	WTC-115.510 115.956	10/11/94	FLOOD
1 WTC-1	1000SF	FP	WTC-115.510 115.961	12/15/94	EMERGENCY CLEANUP
1 WTC-1		FP	WTC-115.510 115.965	01/09/95	CEILING TILES FOUND DISTURBED ON VACANT FLOOR
1 WTC-1	10000SF/10000SF	FP/VAT	WTC-115.510 115.970	03/27/95	RENOVATION FOR NEW TENANT
1 WTC-1		FP FALLOUT	WTC-115.224 115.988	09/18/89	EMERGENCY CLEANUP
1 WTC-1,2	30,000SF	FP	WTC-115.224 115.728	01/01/90	O&M - MISC CLEAN-UP OF FALLOUT MATERIAL
1 WTC-1,2	24312SF	FP	WTC-115.224 115.733	12/14/89	CLEANUP OF ACM FALLOUT-SURFACE CLEANED
1 WTC-1,2		FP	WTC-115.224 115.765	03/16/90	EMERGENCY CONOITION
1 WTC-1,2	108SF	FP FALLOUT	WTC-115.224 115.822	03/25/92	EMERGENCY CONOITION
1 WTC-1,2		FP	WTC-115.224 115.825	05/13/92	
1 WTC-1,2		FP	WTC-115.510 115.847	03/10/94	RE-DESIGN OF CARS
T WTC-1,2		FP FALLOUT	WTC-115.224 115.857	12/15/92	EMERGENCY CLEANUP

PORT AUTHORITY & TENANT
ASBESTOS ABATEMENT PROJECTS

Date:08/13/96
PAGE NUMBER 11

AP=ACOUSTICAL PLASTER
FP=FIREPROOFING

Ct Building	Bestquant	Product	Contnum Jobnum	Start Date	Reason
1 WTC-1,2		FP FALLOUT	WTC-115.510 115.934	05/12/94	EMERGENCY CLEANUP
1 WTC-1,2		FP	WTC-115.510 115.942	07/22/94	INSTALLTION OF NEW FIRE SPEAKERS
1 WTC-1,2		FP	WTC-115.510 115.963	12/27/94	ELEVATOR MAINTENANCE
1 WTC-2	100SF	FP	WTC-115.223 115.223	06/23/87	DEMOLITION AND ALTERATION OF SPACE TO ACCOMODATE NEW TENANT
1 WTC-2	1000SF	FP	EX0-100.367 115.228	11/03/87	RENOVATION, DEMOLITION & ALTERATION OF SPACE TO ACCOMODATE NEW TENANT
1 WTC-2	824SF	FP	WTC-115.225 115.232	09/22/87	O&M-INSTALLATION OF NEW DUCTWORK FOR TENANT (O&M WITTER) AND REINFORCEMENT OF SUPPORT BEAMS AT 5 SEPARATE LOCATIONS
1 WTC-2	35000SF	FP	WTC-115.225 115.234	09/28/87	INSTALLATION OF SPRINKLER SYSTEMS-DEMOLITION AND ALTERATION OF SPACE TO ACCOMODATE NEW TENANT
1 WTC-2	85SF	FP	WTC-115.224 115.239	11/15/88	RENOVATION & ALTERATION OF SPACE TO ACCOMODATE NEW TENANT
1 WTC-2		FP	TAA 115.281	11/08/93	RENOVATION OF FLOORS BY TENANT
1 WTC-2		FP	WTC-942.140 115.284	05/20/94	
1 WTC-2	20SF	ENCAPSULATE FP	WTC-951.154 115.292	08/05/92	
1 WTC-2		FP	WTC-115.510 115.330	08/05/95	DECON SETUP FOR ELECTRICIANS USE DURING WORK IN PROXIMITY TO FP-NO REMOVAL
1 WTC-2	240SF	FP	WTC-115.224 115.702	02/06/89	RENOVATION - INSTALLATION OF PLUMBING LINES
1 WTC-2		FP	WTC-115.224 115.711	03/20/90	ELEVATOR DOOR INSTALLATION

PORT AUTHORITY & TENANT
ASBESTOS ABATEMENT PROJECTS

Date:08/13/96
PAGE NUMBER 12

AP=ACOUSTICAL PLASTER
FP=FIREPROOFING

Ct	Building	Bestquant	Product	Contrum Jobnum	Start Date	Reason
1	WTC-2	250SF/20,000SF	FP/SURFACE AREA CLEANED	WTC-115.224 115.712	05/17/89	RENOVATION - SPOT REMOVALS REQUIRED TO INSTALL NEW EQUIPMENT HANGARS
1	WTC-2	35,000SF	FP	WTC-115.224 115.724	01/01/90	O&M - CLEAN-UP OF FALLOUT MATERIAL
1	WTC-2	35,00SF	FP	WTC-115.224 115.725	01/01/90	O&M - MISC CLEAN-UP OF FALLOUT MATERIAL
1	WTC-2		FP	WTC-115.224 115.764	03/14/90	EMERGENCY CONDIIION
1	WTC-2	1800SF	FP	WTC-115.224 115.783	08/30/91	NO ABATEMENT TAKING PLACE, REPLACEMENT OF EXISTING FP IN ACM AREA
1	WTC-2	1100SF	FP	WTC-115.224 115.787	12/30/91	RENOVATION
1	WTC-2		FP	WTC-115.224 115.791	04/01/92	NON-ACM TEST PROGRAM FOR FIREPROOFING REPLACEMENT
1	WTC-2		FP	WTC-115.224 115.811	09/13/90	NO ABATEMENT. AREA USED FOR PROTECTION EQUIPMENT TEST PURPOSES ONLY
1	WTC-2	324SF	FP FALLOUT	WTC-115.224 115.820	03/09/92	EMERGENCY CONDITION - DUE TO FLOOD IN BUILDING
1	WTC-2	108SF	FP FALLOUT	WTC-115.224 115.835	05/29/92	EMERGENCY CLEANUP
1	WTC-2		FP FALLOUT	WTC-115.224 115.858	12/26/92	EMERGENCY CLEANUP
1	WTC-2		FP FALLOUT	WTC-115.224 115.864	11/28/92	EMERGENCY CLEANUP
1	WTC-2		FP FALLOUT	WTC-115.224 115.879	07/27/93	EMERGENCY CLEANUP
1	WTC-2		FP FALLOUT	WTC-115.224 115.989	08/08/89	EMERGENCY CLEANUP
1	WTC-2		DUCT/ENCAPSULAT ION	T-3491 115.997	08/01/88	RENOVATION - DEMOLITION AND ALTERATION WORK REQUIRED THE ENCAPSULATION OF SOME DUCT WORK AND THE ABATEMENT OF OTHER

PORT AUTHORITY & TENANT
ASBESTOS ABATEMENT PROJECTS

Date:08/13/96
PAGE NUMBER 13

AP=ACOUSTICAL PLASTER
FP=FIREPROOFING

Ct Building	Bestquant	Product	Contrum Jobnum	Start Date	Reason
=====					
1 WTC-2		FP	T-3734 115.999	04/20/87	PERMIT INSTALLATION OF ELECTRICAL CONDUITS
Total					
186					

PORT AUTHORITY & NEWARK
ASBESTOS ABATEMENT PROJECTS

Date:08/13/96
PAGE NUMBER 1

AP=ACOUSTICAL PLASTER
FP=FIREPROOFING

Ct	Building	Bestquant	Product	Contrum Jobnum	Start Date	Reason
1	PN-135		FP	MFP-315.500 315.544	02/14/90	PCU CLEAN UP OF FALLEN ASBESTOS DEBRIS AND ENCAPSULATION OF SPRAY ON ASBESTOS
1	PN-201	4,408SF	FP	EXD-100.368 315.047	08/18/88	NOT REMOVED - MATERIAL CONTAINED TO PROTECT FROM DISTURBANCE BY NEW TENANT (MANER TERMINALS) SEE MALONE TO O'MALLEY 5/9/88 MEMO
1	PN-201	4,408SF CONTAINMENT/40 CUBIC YARDS OF FP	FP	EXD-100.368 315.049	08/10/88	NOT REMOVED MATERIAL CONTAINED TO PROTECT FROM DISTURBANCE BY TENANT. SEE MALONE TO O'MALLEY MEMO
1	PN-201	640SF	FP	MFP-315.500 315.516	02/02/90	IRC- DETERIORATED CONDITION OF ASBESTOS FIREPROOFING
1	PN-201		FP	MFP-315.500 315.517	02/09/90	IRC- CLEANUP OF FALLOUT RESULTING FROM FIREPROOFING
1	PN-201	4408SF	FP	MFP-315.500 315.518	02/09/90	IRC- DETERIORATED CONDITION OF ASBESTOS FIREPROOFING
1	PN-202	1,992SF	FP	EXD-100.368 315.016	04/23/88	NEW INCOMING TENANT DEMANDED THAT ASBESTOS BE REMOVED. SEE MALONE TO O'MALLEY MEMO
1	PN-202		FP	EXD-100.368 315.021	04/12/88	IRC
1	PN-260	4,620SF	FP	EXD-100.368 315.005	04/01/88	WORKERS BEGAN TO REFUSE TO WORK IN MAINTENANCE SHOPS. SEE MEISTER (OSNA) LETTER. MANAGEMENT MADE DECISION TO REMOVE FIREPROOFING.
1	PN-260	4,90SF/175SF/20 3LF	FP/BOILER/PIPE INSULATION	EXD-100.368 315.006	04/11/88	IRC FOR ELECTRICAL ROOM, OTHER AREAS ABATEO AS A RESULT OF WORKER COMPLAINTS. SEE MEISTER (OSNA) LETTER
1	PN-260	13203SF/171SF/7 103SF/2050LF	VAT/FP/OUCL/PIP E	PN-315.011 315.011	09/01/88	RENOVATION- MODIFICATION OF HVAC SYSTEM
1	PN-260	240SF	FP-CLEANUP	EXD-100.375 315.301	03/09/90	EMERGENCY CONDITION

PORT AUTHORITY & TENANT
ASBESTOS ABATEMENT PROJECTS

Date:08/13/96
PAGE NUMBER 1

AP=ACOUSTICAL PLASTER
FP=FIREPROOFING

Ct	Building	Bestquant	Product	Contrum Jobnum	Start Date	Reason
1	PE-1330		FP	MFP-315.500 315.549	02/23/90	IRC
1	PE-1340		FP	MFP-315.500 315.537	10/01/89	IRC-PCU CLEAN UP OF ASBESTOS DEBRIS AND ENCAPSULATION OF ASBESTOS
1	PE-2210		PIPE/FP	MFP-315.500 315.540	02/14/90	IRC
1	PE-2230		FP	PSE-500 315.970	09/22/89	IRC
1	PE-2240		FP/PIPE	EP-110.049 315.042	09/01/88	RENOVATION - PARTIAL DEMOLITION AND ALTERATION OF TENANT SPACE.
1	PE-2240		PIPE/FP	MFP-315.550 315.575	01/27/92	RENOVATION - ORIGINAL SCOPE OF WORK (315.042) INCREASED
1	PE-2270		FP	PSE-500 315.965	04/22/89	IRC
1	PE-2270		FP	PSE-500 315.966	06/06/89	IRC
1	PE-2270		FP	PSE-500 315.967	06/05/89	IRC
1	PE-2270		FP	PSE-500 315.968	05/31/89	IRC
1	PE-2270		FP	PSE-500 315.969	05/29/89	IRC
1	PE-2280	2040SF/41LF	FP/PIPE	MFP-315.500 315.526	09/07/90	RENOVATION
1	PE-2280		PIPE/FP	MFP-315.500 315.558	04/05/90	IRC
Total						
13						

PORT AUTHORITY & TWA
ASBESTOS ABATEMENT PROJECTS

Date:08/13/96
PAGE NUMBER 2

AP=ACOUSTICAL PLASTER
FP=FIREPROOFING

Ct	Building	Bestquant	Product	Continum Jobnum	Start Date	Reason
1	PN-260		PIPE FITTINGS/FP FALLOUT	EXD-100.375 315.302	04/27/90	EMERGENCY CONDITION
1	PN-260	48SF	FP-ENCLOSURE OF CEILING WITHIN CLOSET	MFP-315.500 315.519	04/20/89	RENOVATION - TO PROVIDE SAFE ACCESS TO TELEPHONE CLOSET FOR REPAIR MEN. TELEPHONE LINES MOVED TO TEMP TRAILERS FOR PA STAFF DURING BLDG RENOVATION
1	PN-260		FP	PSE-500 315.989	04/14/88	IRC
1	PN-260		FP	PSE-500 315.990	11/14/88	IRC
1	PN-266		PIPE/FP	MFP-315.500 315.551	11/02/89	IRC-PCU CLEAN UP OF ASBESTOS FALLEN DEBRIS AND ENCAPSULATION OF ASBESTOS INSULATION ON BEAMS
1	PN-303	2,176SF	FP	MFP-315.500 315.520	07/21/89	IRC- DETERIORATED CONDITION OF FIREPROOFING HAS RESULTED IN THE AREA BEING DESIGNATED AS IRC
Total 18						

PORT AUTHORITY & TENANT
ASBESTOS ABATEMENT PROJECTS

Date:08/13/96
PAGE NUMBER 1

AP=ACOUSTICAL PLASTER
FP=FIREPROOFING

Ct	Building	Bestquant	Product	Continum Jobnum	Start Date	Reason
1	HH-SCALE HOUSE	3,017SF/421LF/1 50SF	FP/PIPE/BOILER	PO-29437 315.022	05/15/88	RENOVATION - PARTIAL DEMOLITION AND ALTERATION OF SPACE
Total	1					

PORT AUTHORITY & TENANT
ASBESTOS ABATEMENT PROJECTS

Date:08/13/96
PAGE NUMBER 1

AP=ACOUSTICAL PLASTER
FP=FIREFPROOFING

Ct	Building	Bestquant	Product	Contract Jobnum	Start Date	Reason
1	JFK-053	800SF	FP	Y-5956 215.016	11/07/88	RENOVATION - ALTERATION OF SPACE TO ACCOMMODATE NEW RETAIL SHOP
1	JFK-053	530SF	FP	Y-6039 215.022	10/10/88	RENOVATION OF SPACE FOR NEW RETAIL SHOP
1	JFK-053		FP	Y-6062A 215.048	02/17/89	RENOVATION
1	JFK-053		PIPE/FITTINGS/F P	Y-6074A 215.052	05/12/89	RENOVATION
1	JFK-053		FP	Y-6068A 215.062	05/08/89	RENOVATION
1	JFK-053		FP	Y-6112 215.063	05/26/89	RENOVATION
1	JFK-053		FP	Y-6123A 215.071	05/31/90	RENOVATION OF GATE AREA
1	JFK-053		FP	Y-6110A 215.072	07/21/89	RENOVATION OF SUPPLEMENTAL AIR CONDITIONING SYSTEM
1	JFK-053		FP	Y-6142A 215.076	10/14/89	REPAIR
1	JFK-053		FP	Y-6061B 215.087	02/08/90	RENOVATION
1	JFK-053		FP	Y-6256A 215.125	05/17/90	RENOVATION
1	JFK-053		PIPE/DUCT/FP	Y-6263A 215.147	11/20/90	RENOVATION
1	JFK-053		FP	Y-6522A 215.218	08/01/92	RENOVATION
1	JFK-053		FP	Y-6529A 215.222	09/02/92	RENOVATION
1	JFK-053	3300SF/4200SF	VAT/FP	Y-6533A 215.223	09/17/92	RENOVATION
1	JFK-053	500SF/5700SF	VAT/FP	Y-6566A 215.252	01/27/93	RENOVATION

PORI AUTHORITY & JENANI
ASBESTOS ABATEMENT PROJECTS

Date:08/13/96
PAGE NUMBER 2

AP=ACOUSTICAL PLASTER
FP=FIREPROOFING

Ct	Building	Bestquant	Product	Continum Jobnum	Start Date	Reason
1	JFK-053		FP	Y-6566.01A 215.254	03/08/93	RENOVATION
1	JFK-053	35000SF/36000SF	VAT/FILLINGS/OU C1/FP	Y-6566B 215.260	05/24/93	RENOVATION
1	JFK-053	220SF/6745SF	VAT/FP	Y-6566.05A 215.267	03/31/93	RENOVATION
1	JFK-053		FP	Y-6566.11A 215.404	10/06/94	RENOVATION
1	JFK-053	2000SF	FP	Y-6566.12A 215.433	01/31/95	RENOVATION
1	JFK-053		FP/PIPE	Y-5813 215.966	01/24/87	RENOVATION
1	JFK-053		FP	Y-5784 215.968	03/16/88	RENOVATION
1	JFK-053		FP	Y-5906A 215.969	01/02/89	RENOVATION
1	JFK-053		FP	Y-5755 215.973	05/12/88	RENOVATION
1	JFK-053,054		FP	Y-6514A 215.215	08/03/92	RENOVATION
1	JFK-053,054		FP	Y-6809A 215.452	07/01/95	RENOVATION
1	JFK-054		VAT/TRANSITE/FP /PIPING/PIPE ELBOWS	Y-6565A 215.273	07/12/93	RENOVATION
1	JFK-054		FP	Y-6565.06A 215.434	12/01/94	RENOVATION
1	JFK-054	264SF	FP	Y-6757A 215.438	03/15/95	RENOVATION
1	JFK-054	440SF	FP	Y-6565.03A 215.439	02/27/95	RENOVATION
1	JFK-055		VAT/PIPE/FITTIN GS/OU/C1/AP	Y-6160A 215.079	10/01/89	**RENOVATION

PORT AUTHORITY & TENANT
ASBESTOS ABATEMENT PROJECTS

Date:08/13/96
PAGE NUMBER 3

AP=ACOUSTICAL PLASTER
FP=FIREPROOFING

Ct	Building	Bestquant	Product	Continum Jobnum	Start Date	Reason
1	JFK-055	2900LF/3620/274 00/16400SF/8700 SF/16240SF/1500 /105000	PIPE INSULATION/PIPE FITTINGS/FP/TRA NSITE/VAT/AP/FI REBLANKET/ROOFI NG	Y-6666 215.287	10/11/94	DEMOLITION OF BUILDING #55
1	JFK-055	300LF/800#/4700 0SF/16240SF	PIPE INSULATON/ PIPE FITTINGS/ VAT/ AP	Y-6666A 215.287A	10/11/94	DEMOLITION OF BUILDING #55
1	JFK-055	600LF/1400/2100 0SF/400SF/900SF /1800SF/1500SF	PIPE INSULATION/ FITTINGS/ DUCT INSULATION/ FP/ TRANSITE/ VAT/ FIREBLANKET	Y-6666B 215.287B	10/11/94	DEMOLITION OF BUILDING #55
1	JFK-055	27000SF/150LF/8 000SF/1000SF/70 #/45000SF	FP/PIPE INSULATION/TRAN SITE/ VAT/ PIPE FITTING/ ROOF	Y-6666E 215.287E	10/11/94	DEMOLITION OF BUILDING #55
1	JFK-055	25SF/9800SF	AP/CLEANUP	EXO-100.374 215.301	01/04/90	EMERGENCY CONOITION
1	JFK-055	2000SF	AP	EXO-100.374 215.304	03/07/90	EMERGENCY CONOITION
1	JFK-055	450SF	AP	JFK-215.590 215.367	03/08/94	IRC - 100 SF OF AP FELL FROM A CANOPY DUE TO A WATER LEAK IN THE ROOF; 400-500SF OF AP REMAINED SATURATED AND NEEDED TO BE REMOVED AS WELL
1	JFK-056,057		AP	Y-6480B 215.248	02/25/93	RENOVATION
1	JFK-056,057		FP	Y-6480C 215.249	01/20/93	RENOVATION
1	JFK-057		FP/F-TILE	Y-5941B 215.018	08/11/88	RENOVATION AND ALTERATION OF TENANT SPACE.
1	JFK-057		FP	Y-6088A 215.058	04/12/89	RENOVATION
1	JFK-057		FP/CLEANUP	Y-5964A 215.073	07/24/89	RENOVATION

PORJ AUTHORITY & TENANT
ASBESTOS ABATEMENT PROJECTS

Date:08/13/96
PAGE NUMBER 4

AP=ACOUSTICAL PLASTER
FP=FIREPROOFING

Ct	Building	Bestquant	Product	Continum Jobnum	Start Date	Reason
1	JFK-057		FP	Y-6060B 215.080	09/25/89	RENOVATION
1	JFK-057		PIPE/FP	Y-6060C 215.081	10/16/89	RENOVATION
1	JFK-057		VAT/PIPE ELBOWS/FP	Y-6060D 215.082	01/15/90	RENOVATION/DEMOLITION
1	JFK-057		PIPE ELBOWS/FP/TRANS ITE	Y-6060E 215.102	03/01/90	DEMOLITION/RENOVATION
1	JFK-057		FP	Y-6060F 215.118	06/04/90	RENOVATION
1	JFK-057		FP	Y-6060J 215.120	06/04/90	RENOVATION
1	JFK-057		FP	G-6060J 215.128	07/01/90	RENOVATION
1	JFK-057		FP	Y-6060K 215.129	08/01/90	RENOVATION
1	JFK-057		FP	Y-6060L 215.130	08/03/90	RENOVATION
1	JFK-057		FP	Y-6060M 215.133	08/15/90	RENOVATION
1	JFK-057		FP	Y-6337A 215.164	03/01/91	RENOVATION
1	JFK-057		AP	Y-6060N 215.168	04/29/91	RENOVATION
1	JFK-057		FP	Y-6060P 215.169	06/03/91	RENOVATION
1	JFK-057		FP	Y-6422A 215.178	09/16/91	RENOVATION
1	JFK-057		ELBOWS/FP	Y-6465A 215.197	04/02/92	RENOVATION
1	JFK-057		AP	Y-6480F 215.289	12/06/93	RENOVATION

PORT AUTHORITY & TENANT
ASBESTOS ABATEMENT PROJECTS

Date:08/13/96
PAGE NUMBER 5

AP=ACOUSTICAL PLASTER
FP=FIREFPROOFING

Ct	Building	Bestquant	Product	Contrum Jobnum	Start Date	Reason
1	JFK-057		FP	Y-6480.07A 215.414	07/15/94	RENOVATION
1	JFK-057	2703SF	FP	Y-6480.07B 215.417	09/01/94	RENOVATION
1	JFK-057		FP	Y-6480.07C 215.443	03/20/95	RENOVATION
1	JFK-057	3840SF	FP	JFK-215.550 215.551	06/14/90	STRUCTUAL INTEGRITY INSPECTIONS
1	JFK-057		FP	Y-5823 215.967	05/04/87	RENOVATION
1	JFK-058-HANG AR-08	48SF-ABAIED/720 SF CLEANED/192SF CLEANED	AP	JFK-215.500 215.509	12/01/89	O&M PREPARATION FOR INTEGRITY INSPECTION
1	JFK-060	8SF	AP	Y-6299 215.139	09/05/90	IRC CONDITION AS DETERMINED BY AMCO
1	JFK-060		AP	Y-6432B 215.407	07/01/94	RENOVATION
1	JFK-060-HANG AR-12		AP	Y-6632A 215.284	11/11/93	RENOVATION
1	JFK-067		FP	Y-6156A 215.089	11/17/89	** RENOVATION
1	JFK-067	7730SF	FP	Y-6529A 215.245	06/18/94	RENOVATION
1	JFK-067		FP/VAT	Y-6725A 215.427	02/05/95	RENOVATION
1	JFK-067		FP	JFK-215.550 215.557	07/23/90	** STRUCTUAL INTEGRITY INSPECTION
1	JFK-067		FP FALLOUT	JFK-215.550 215.564	10/11/91	** IRC
1	JFK-069		FP	Y-5855 215.988	09/25/87	RENOVATION - ENTIRE BLDG.
1	JFK-081	6480SF	AP	JFK-215.550 215.321	10/18/91	EMERGENCY CONDITION

PORT AUTHORITY & TENANT
ASBESTOS ABATEMENT PROJECTS

Date:08/13/96
PAGE NUMBER 6

AP=ACOUSTICAL PLASTER
FP=FIREPROOFING

Ct	Building	Bestquant	Product	Continum Jobnum	Start Date	Reason
1	JFK-081,082	16000SF/ 3208LF/ 458/ 155SF/ 5000SF/ 19400SF	FP/ PIPE/ FITTINGS/ BREECHING/ WALL PLASTER/ GALBESTOS	JFK-215.047 215.047	10/19/89	** DEMOLITION - ENTIRE BLOC. #81 & PART OF BLOC. #82
1	JFK-146	256SF	FP	JFK-215.550 215.554	07/23/90	STRUCTUAL INTEGRITY REPORT
1	JFK-178	256SF	FP/DEBRIS	JFK-215.500 215.514	04/08/90	O&M - PREPARATION FOR INTEGRITY INSPECTION
1	JFK-178	4,323SF (4TH FLOOR)/210SF (BASEMENT) TOTAL 4,533SF	FP	JFK-110.057 215.994	02/17/87	RENOVATION - ALIARATION OF SPACE FOR NEW TENANT
1	JFK-213	12368SF/9276SF/ 412LF	FP/OUCL INSULATION/PIPE INSULATION	Y-6517A 215.216	06/07/93	RENOVATION
1	JFK-213		FP	Y-6517B 215.272	05/12/93	RENOVATION
1	JFK-213	320SF	FP	JFK-215.550 215.555	07/23/90	STRUCTUAL INYEGRITY INSPECTION
1	JFK-IAB		WRAP & CLEAN-UP	JFK-215.550 215.599	05/09/94	
1	JFK-IAB-050		FP	Y-5901 215.009	03/28/88	RENOVATION - ALIARATION OF SPACE TO ACCOMODATE NEW RETAIL SHOPS
1	JFK-IAB-050	1755SF	AP	JFK-215.500 215.035	11/26/88	RENOVATION OF CUSYOMS HALL FOR NEW TENANT LOUNGE
1	JFK-IAB-050	8SF	AP	JFK-215.550 215.317	06/05/91	EMERGENCY CONDIITION
1	JFK-IAB-050	10 CU YOS	FP - FALLOU1	JFK-215.500 215.516	11/16/89	IRC - DISPOSAL OF ACM FALLOU 10 BAGS
1	JFK-IAB-050	18SF	AP	JFK-215.500 215.518	05/15/90	O&M
1	JFK-IAB-050	600SF	AP	JFK-215.500 215.535	09/13/90	RENOVATION - INSTALLATION OF SECURITY SYSTEM

PORT AUTHORITY & TENANT
ASBESTOS ABATEMENT PROJECTS

Date:08/13/96
PAGE NUMBER 7

AP=ACOUSTICAL PLASTER
FP=FIREFPROOFING

Ct	Building	Bestquant	Product	Contrum Jobnum	Start Date	Reason
1	JFK-IAB-050		AP	JFK-215.500 215.536	10/16/90	EMERGENCY CONOITION
1	JFK-IAB-050	2,695SF	AP	EXO-100.367 215.991	08/01/87	RENOVATION - ALTERATION OF AREA FOR NEW TENANT OCCUPANCY
1	JFK-IAB-050, 051,052		PIPE INSULATION/WRAP	JFK-215.550 215.338	06/05/92	EMERGENCY CONOITION
1	JFK-IAB-050, 051,052		AP	JFK-215.590 215.369	05/13/94	EMERGENCT CONOITION
1	JFK-IAB-050, 051,052		AP/PIPE FITTINGS	JFK-215.550 215.573	02/24/92	RENOVATION
1	JFK-IAB-050, 052		AP	JFK-215.550 215.359	06/25/93	EMERGENCT CONOITION
1	JFK-IAB-051	2500SF	AP	Y-6169A 215.088	01/29/90	RENOVATION OF PUBLIC WAITING
1	JFK-IAB-051		AP	Y-6152A 215.109	03/19/90	RENOVATION
1	JFK-IAB-051		AP	Y-6153A 215.110	03/19/90	RENOVATION
1	JFK-IAB-051	2413SF	AP	Y-6286A 215.134	08/15/90	RENOVATION
1	JFK-IAB-051	40,000SF	AP	Y-6191A 215.142	10/15/90	RENOVATION
1	JFK-IAB-051		AP	T-6191A 215.142	10/15/90	RENOVATION
1	JFK-IAB-051	APPROX. BSF	AP	JFK-215.550 215.333	05/14/92	IRC - CLEAN UP PERFORMEO OUE TO WATER OAMAGE
1	JFK-IAB-051	480SF	AP	Y-6717A 215.436	12/19/94	RENOVATION
1	JFK-IAB-051	2600SF	AP	JFK-215.500 215.533	08/07/90	RENOVATION - SHOP ALTERATIONS
1	JFK-IAB-051	750SF/20LF	AP	JFK-215.550 215.580	10/05/94	RENOVATION - EXPANSION OF RESTROOMS
1	JFK-IAB-051	730SF	AP	JFK-215.550 215.582	11/29/93	RENOVATION

PORT AUTHORITY & TENANT
ASBESTOS ABATEMENT PROJECTS

Date:08/13/96
PAGE NUMBER 8

AP=ACOUSTICAL PLASTER
FP=FIREPROOFING

Ct	Building	Bestquant	Product	Continum Jobnum	Start Date	Reason
1	JFK-IAB-051	1800SF	AP	JFK-215.550 215.593	03/31/93	VENOING AREA TO BE DEMOLISNEO
1	JFK-IAB-051	50SF	AP	JFK-215.690 215.678	11/23/95	INSTALLATION OF ALARM SYSTEM
1	JFK-IAB-051, 052	NO ACM REMOVED	AP	JFK-215.590 215.636	02/07/94	CLEANING AND PREPARING CEILING FOR PAINTING
1	JFK-IAB-051, 052	500SF	AP	JFK-215.590 215.653	10/27/94	REPAIR OF DAMAGED ACOUSTICAL PLASTER CEILINGS - INTERIM IMPROVEMENT PROGRAM
1	JFK-IAB-052	2000SF	AP	EXO-100.374 215.312	02/11/91	EMERGENCY CONOITION
1	JFK-IAB-052		AP	EXO-100.374 215.314	02/25/91	EMERGENCY CONOITION
1	JFK-IAB-052	66SF	AP	EXO-100.374 215.315	04/02/91	EMERGENCY CONOITION
1	JFK-IAB-052	2000SF	AP	EXO-100.374 215.316	05/16/91	EMERGENCY CONOITION
1	JFK-IAB-052		AP	JFK-215.550 215.357	06/21/93	EMERGENCY CONOITION
1	JFK-IAB-052	110SF	AP	JFK-215.590 215.373	01/10/95	IRC
1	JFK-IAB-052	150SF	AP	JFK-215.590 215.374	01/16/95	IRC
1	JFK-IAB-052	260SF	AP	JFK-215.500 215.534	08/07/90	RENOVATION - SHOP ALTERATIONS
1	JFK-IAB-052	640SF	AP	JFK-215.550 215.579	01/19/93	RENOVATION
1	JFK-IAB-052	1890SF/50LF	AP	JFK-215.550 215.581	07/01/92	RENOVATION
1	JFK-IAB-052	500SF	AP	JFK-215.550 215.589	03/31/93	RENOVATION
1	JFK-IAB-052	380SF	AP	JFK-215.550 215.592	11/08/93	RENOVATION

PORT AUTHORITY & TIANJI
ASBESTOS ABATEMENT PROJECTS

Date:08/13/96
PAGE NUMBER 9

AP=ACOUSTICAL PLASTER
FP=FIREPROOFING

Ct	Building	Bestquant	Product	Continum Jobnum	Start Date	Reason
1	JFK-1AB-052		AP	JFK-215.590 215.617	01/05/94	REPLACEMENT OF EXISTING SPRINKLER HEADS
1	JFK-VARIOUS BUILDINGS		AP	JFK-215.550 215.569	01/31/92	RENOVATION - INSTALLATION OF OMETIC HOT WATER HEATERS
1	JFK-VARIOUS BUILDINGS		FP	JFK-215.550 215.622	07/19/93	COGEN PROJECT -MISC REMOVALS, REPAIRS, AND/OR CLEANUPS
	total					
	126					

PORT AUTHORITY TENANT
ASBESTOS ABATEMENT PROJECTS

Date:08/13/96
PAGE NUMBER 1

AP=ACoustICAL PLASTER
FP=FIREPROOFING

Ct	Building	Bestquant	Product	Continum Jobnum	Start Date	Reason
1	EWR-105	16SF(50+ 2"MOLES)/270SF	FP/CLEANUP/AP	EWR-215.920 215.153	02/11/91	O&M - INSTALLATION WORK FOR THE NEW REVENUE CONTROL SYSTEM
1	EWR-TERM-A	100DSF	FP	NA-155 215.182	02/06/92	RENOVATION
1	EWR-TERM-A	<3000SF	FP	NA-157 215.189	09/21/92	RENOVATION
1	EWR-TERM-A	5900SF	FP	NA-147 215.192	04/13/92	RENOVATION
1	EWR-TERM-A	25 CUYDS	CEILING TILE/AP	NA-161 215.193	10/19/93	RENOVATION
1	EWR-TERM-A	3330SF	AP	NA-168 215.242	05/13/93	RENOVATION
1	EWR-TERM-A	275SF	FP	EWR-124.017 215.246	01/06/93	RENOVATION - INSTALLATION OF NEW STEEL BEAM
1	EWR-TERM-A	150DSF	FP	NA-178 215.282	02/14/94	RENOVATION
1	EWR-TERM-A	500SF	FP	EWR-124.017 215.345	09/17/92	EMERGENCY CONDITION
1	EWR-TERM-A	1500SF	FP	NA-195 215.409	08/16/94	OPERATIONS AND MAINTENANCE
1	EWR-TERM-A	1200SF	FP	NA-191 215.411	09/22/94	RENOVATION
1	EWR-TERM-A	4000SF	FP	NA-203 215.422	11/28/94	EXPANSION OF THE RED CARPET CLUB
1	EWR-TERM-A	2000SF	FP	MF-415.750 215.934	09/13/93	TO ALLOW FOR RENOVATION-NEW TENANT
1	EWR-TERM-A	140DSF/10LF	FP/PIPE	EWR-215.930 215.949	04/18/95	RENOVATION/NEW STORE FRONTS TO BE CONSTRUCTED;STRUCTURAL WORK WILL IMPACT FIREPROOFING
1	EWR-TERM-A	1550SF/8#	FP/PIPE	EWR-215.930 215.950	03/27/95	RENOVATION/NEW STORE FRONTS TO BE CONSTRUCTED;STRUCTURAL WORK WILL IMPACT FIREPROOFING
1	EWR-TERM-A	1100SF/BLF	FP/PIPE	EWR-215.930 215.951	03/07/95	RENOVATION/NEW STORE FRONTS TO BE CONSTRUCTED;STRUCTURAL WORK WILL IMPACT FIREPROOFING

PORT AUTHORITY & TENANT
ASBESTOS ABATEMENT PROJECTS

Date:08/13/96
PAGE NUMBER 2

AP=ACOUSTICAL PLASTER
FP=FIREPROOFING

Ct	Building	Bestquant	Product	Continum Jobnum	Start Date	Reason
1	EWR-TERM-A	300SF	FP	EWR-215.930 215.952	03/27/95	RENOVATION/NEW STORE FRONTS TO BE CONSTRUCTED;STRUCTURAL WORK WILL IMPACT FIREPROOFING
1	EWR-TERM-A	1250SF/10LF	FP/PIPE	EWR-215.930 215.953	03/07/95	RENOVATION/NEW STORE FRONTS TO BE CONSTRUCTED;STRUCTURAL WORK WILL IMPACT FIREPROOFING
1	EWR-TERM-A	28000SF	FP	EWR-215.930 215.955	10/05/95	EMERGENCY CEILING REPLACEMENT DUE TO POOR CEILING SUPPORT SYSTEM
1	EWR-TERM-A	1200SF	FP	NIA-120 215.999	01/15/88	PRELIMINARY WORK PERFORMED BY PA CONTRACT SUBSEQUENT TO TENANT OCCUPYING SPACE
1	EWR-TERM-A,B	16000SF	FP-CLEANUP OF CEILING AREAS	NIA-100.504 215.040	12/01/88	REQUIRED TO ASSURE A SAFE WORK AREA AND PREVENT CONTAMINATION OF PUBLIC AREAS FOR STRUCTUAL INTEGRITY REPORT.
1	EWR-TERM-A,B	20000SF/60000SF /8000SF	AP/ROOFING/FP	EWR-124.014 215.177	11/13/91	RENOVATION
1	EWR-TERM-A,B	100SF	FP	EWR-124.017 215.243	10/29/92	RENOVATION
1	EWR-TERM-A,B	8SF	FP	EWR-215.920 215.920	02/08/92	IRC
1	EWR-TERM-B	2300SF/100SF/10 670SF/750SF	ACM/FP/FP/ACM (SEE MISC_REC MEMO)	NB-148 215.084	02/21/90	RENOVATION
1	EWR-TERM-B	14430SF	FP	NB-154 215.086	02/05/90	RENOVATION
1	EWR-TERM-B	4600SF	FP	NB-165 215.116	05/16/90	RENOVATION
1	EWR-TERM-B	5000SF/250LF	FP/PIPE	EWR-215.148 215.148	04/22/91	RENOVATION OF BAGGAGE SYSTEM TO ACCOMMODATE NEW INTERNATIONAL ARRIVALS FACILITY
1	EWR-TERM-B	50LF/1500SF	PIPE/FP	NB-182 215.173	10/28/92	RENOVATION
1	EWR-TERM-B	500SF	FP	EWR-124.017 215.229	09/22/92	RENOVATION - CONNECTION OF NEW BEAMS TO EXISTING CEILING BEAM

PORT AUTHORITY & TENANT
ASBESTOS ABATEMENT PROJECTS

Date:08/13/96
PAGE NUMBER 3

AP=ACOUSTICAL PLASTER
FP=FIREPROOFING

Ct	Building	Bestquant	Product	Continuum Jobnum	Start Date	Reason
1	EWR-TERM-B	200SF	FP	EWR-124.017 215.231	09/22/92	RENOVATION - INSTALLATION OF NEW COLUMN
1	EWR-TERM-B	995SF	FP	EWR-124.017 215.247	01/06/93	RENOVATION - INSTALLATION OF NEW BEAM
1	EWR-TERM-B	100SF	FP/CEILING TILES	EWR-110.045 215.255	09/27/93	RENOVATION - FOR CONVEYOR INSTALLATION AND REMOVALS
1	EWR-TERM-B	5700SF	AP/FP	MF-415.750 215.256	08/17/93	RENOVATION
1	EWR-TERM-B	40LF/6600SF	PIPE INSULATION/FP/A P/VAT	EWR-174.050 215.288	09/19/94	RENOVATION OF BUILDING
1	EWR-TERM-B	700SF	FP	EWR-174.048 215.472	10/23/95	RENOVATION
1	EWR-TERM-B	4000SF/900SF	FP/TILE-MASTIC	N-2467 215.475	11/01/95	RENOVATION
1	EWR-TERM-B	300SF	FP	N-2465.01 215.482	12/16/95	RENOVATION
1	EWR-TERM-B	1100SF	FP	N-2481 215.488	03/11/96	RENOVATION
1	EWR-TERM-B	2552SF/1600SF/8 40SF	FP-ABATEMENT/FP -ENCAPSULATION/ FP-CLEANING OF CEILING TILES	EWR-215.400 215.901	02/13/89	RENOVATION-CONSTRUCTION OF INTERNATIONAL ARRIVALS FACILITY
1	EWR-TERM-B	300SF/45000SF	FP ABATEMENT/CLEAN ING OF CONTAMINATED CEILING STRUCTURES	EWR-215.400 215.902	02/13/89	RENOVATION - CONSTRUCTION OF INTERNATIONAL ARRIVALS FACILITY
1	EWR-TERM-B	3600SF	FP/CLEANUP(CEIL ING TILES)	EWR-215.400 215.903	02/23/89	RENOVATION - CONSTRUCTION OF INTERNATIONAL ARRIVALS FACILITY
1	EWR-TERM-B	1080SF	FP	EWR-215.400 215.904	03/28/89	RENOVATION- CONSTRUCTION OF INTERNATIONAL ARRIVALS AREA, CONSTRUCT NEW STRUCTUAL SUPPORTS FOR CONVEYORS AND MISCELLANEOUS ABATEMENT OF ARRIVALS LEVEL

PORT AUTHORITY & TENANT
ASBESTOS ABATEMENT PROJECTS

Date:08/13/96
PAGE NUMBER 4

AP=ACOUSTICAL PLASTER
FP=FIREPROOFING

Ct	Building	Bestquant	Product	Continum Jobnum	Start Date	Reason
1	EWR-TERM-B	1556sf	FP	EWR-503 215.909	10/30/89	RENOVATION - INSTALLATION OF PEOPLE MOVER SYSTEM
1	EWR-TERM-B	700sf	FP	MF-415.500 215.911	04/16/90	INSTALLATION OF NEW BAGGAGE CONVEYOR
1	EWR-TERM-B	10sf	FP	EWR-215.920 215.912	05/16/91	O&M - CONNECTION OF AIR CONDITIONING UNIT TO STRUCTUAL SYSTEM
1	EWR-TERM-B	8sf	FP FALLOUT	EWR-215.920 215.917	06/17/91	EMERGENCY CONOITION
1	EWR-TERM-B	6sf	FP	EWR-215.920 215.925	07/15/92	O&M - BEAM NEEOS REPAIR(REBOLTED)
1	EWR-TERM-B	9200sf/4000sf	FP/ROOFING	EWR-215.930 215.941	07/25/94	SELECTIVE BUILDING OEMOLITION
1	EWR-TERM-B	1900sf/300sf	VA1/FP	EWR-215.930 215.944	12/05/94	RENOVATION
1	EWR-TERM-B	12sf	FP	EWR-215.930 215.946	11/07/94	TO ACCOMMODATE LIGHTING INSTALLATION
1	EWR-TERM-B	750sf	FP	EWR-215.930 215.947	01/09/95	REPLACEMENT OF CEILING
1	EWR-TERM-B	3000sf/20lf	FP/PIPE	EWR-215.930 215.948	06/01/95	RENOVATION/STRUCTURAL CONNECTION TO STOREFRONT
1	EWR-TERM-B	21sf	FP	EWR 215.930 215.954	06/14/95	BLOCKING OF ORAINS BY FIS CONSTRUCTION OVERNEAO

Total
54